


# Keep Your Skirt On



**C**rewmen, don't underestimate the importance of using **every** skirt bracket screw, NSN 5305-00-724-7222, on your M2/M3-series Bradley.

Those skirts are **very** heavy. So, if even one of the three bracket screws vibrates loose, a lot of pressure is put on the remaining two. Pretty soon, you're left with no screws and a missing skirt.



Eyeball the skirt bracket screws before and after every operation. If any are loose, tell your mechanic before they turn up missing.

He'll replace loose screws and torque the replacements to 151–166 lb-ft.